

Jon A. Franke
Site Vice President

PPL Susquehanna, LLC
769 Salem Boulevard
Berwick, PA 18603
Tel. 570.542.2904 Fax 570.542.1504
jfranke@pplweb.com



NOV 13 2013

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555


**SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-388/2013-003-00
UNIT 2 LICENSE NO. NPF-22
PLA-7103**

Docket No 50-388

Attached is Licensee Event Report (LER) 50-388/2013-003-00. On September 14, 2013, at approximately 0330 hours, the Susquehanna Steam Electric Station (SSES) Unit 2 reactor was manually scrammed due to loss of the reactor feedwater pumps (RFPs) when reactor water level reached +54 inches while transitioning the feedwater Integrated Control System (ICS) for the 'A' RFP from flow control mode to discharge pressure mode. The Reactor Core Isolation Cooling (RCIC) system was manually initiated for reactor water level control. This LER is being submitted in accordance with 10 CFR 50.73(a)(2)(iv)(A), for an event or condition that resulted in the manual actuation of the RPS and RCIC system.

There were no actual consequences to the health and safety of the public as a result of these events.

No commitments were identified in this submittal.


J. A. Franke

Attachment: LER 50-388/2013-003-00

Copy: NRC Region I
Mr. J. Greives, NRC Sr. Resident Inspector
Mr. J. Whited, NRC Project Manager
Mr. L. Winker, PA DEP/BRP

NRC FORM 366 (10-2010)		U.S. NUCLEAR REGULATORY COMMISSION		APPROVED BY OMB: NO. 3150-0104		EXPIRES: 10/31/2013	
<h2 style="margin: 0;">LICENSEE EVENT REPORT (LER)</h2> <p style="margin: 5px 0;">(See reverse for required number of digits/characters for each block)</p>							
1. FACILITY NAME Susquehanna Steam Electric Station Unit 2				2. DOCKET NUMBER 05000388		3. PAGE 1 OF 3	
4. TITLE Unit 2 Manual Reactor Scram due to Loss of Reactor Feedwater Pumps							
5. EVENT DATE			6. LER NUMBER			7. REPORT DATE	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY
09	14	2013	2013	- 003 -	00	11	13
						2013	
8. OTHER FACILITIES INVOLVED							
FACILITY NAME						DOCKET NUMBER	
						05000	
FACILITY NAME						DOCKET NUMBER	
						05000	
9. OPERATING MODE		11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§: (Check all that apply)					
Mode 1		<input type="checkbox"/> 20.2201(b) <input type="checkbox"/> 20.2203(a)(3)(i) <input type="checkbox"/> 50.73(a)(2)(i)(C) <input type="checkbox"/> 50.73(a)(2)(vii)					
		<input type="checkbox"/> 20.2201(d) <input type="checkbox"/> 20.2203(a)(3)(ii) <input type="checkbox"/> 50.73(a)(2)(ii)(A) <input type="checkbox"/> 50.73(a)(2)(viii)(A)					
10. POWER LEVEL		<input type="checkbox"/> 20.2203(a)(1) <input type="checkbox"/> 20.2203(a)(4) <input type="checkbox"/> 50.73(a)(2)(ii)(B) <input type="checkbox"/> 50.73(a)(2)(viii)(B)					
		<input type="checkbox"/> 20.2203(a)(2)(i) <input type="checkbox"/> 50.36(c)(1)(i)(A) <input type="checkbox"/> 50.73(a)(2)(iii) <input type="checkbox"/> 50.73(a)(2)(ix)(A)					
14%		<input type="checkbox"/> 20.2203(a)(2)(ii) <input type="checkbox"/> 50.36(c)(1)(ii)(A) <input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A) <input type="checkbox"/> 50.73(a)(2)(x)					
		<input type="checkbox"/> 20.2203(a)(2)(iii) <input type="checkbox"/> 50.36(c)(2) <input type="checkbox"/> 50.73(a)(2)(v)(A) <input type="checkbox"/> 73.71(a)(4)					
		<input type="checkbox"/> 20.2203(a)(2)(iv) <input type="checkbox"/> 50.46(a)(3)(ii) <input type="checkbox"/> 50.73(a)(2)(v)(B) <input type="checkbox"/> 73.71(a)(5)					
		<input type="checkbox"/> 20.2203(a)(2)(v) <input type="checkbox"/> 50.73(a)(2)(i)(A) <input type="checkbox"/> 50.73(a)(2)(v)(C) <input type="checkbox"/> OTHER					
20.2203(a)(2)(vi)		<input type="checkbox"/> 50.73(a)(2)(i)(B) <input type="checkbox"/> 50.73(a)(2)(v)(D)					
12. LICENSEE CONTACT FOR THIS LER							
Facility Name Brenda W. O'Rourke, Senior Engineer - Nuclear Regulatory Affairs						Telephone Number (Include Area Code) (570) 542-1791	
CAUSE	SYSTEM	COMPONENT	MANU-FACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT
14. SUPPLEMENTAL REPORT EXPECTED					15. EXPECTED SUBMISSION DATE		
<input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE)					<input checked="" type="checkbox"/> NO		
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)							
<p>On September 14, 2013, at approximately 0330 hours, the SSER Unit 2 reactor was manually scrambled following the loss of all Reactor Feedwater Pumps (RFPs) due to high reactor water level. This occurred while transitioning the feedwater Integrated Control System (ICS) for the 'A' RFP from flow control mode to discharge pressure mode. Reactor water level rose to +54 inches causing a trip of the reactor feedwater pumps. Operations subsequently took the mode switch to shutdown to manually scram the reactor. All control rods inserted. There were no automatic Emergency Core Cooling System initiations. No steam relief valve opened during the event. No containment isolations occurred. All safety systems operated as expected. The Reactor Core Isolation Cooling (RCIC) system was manually initiated for reactor water level control until a RFP was recovered. RCIC was manually shut down once a RFP was restored. This LER is being submitted in accordance with 10 CFR 50.73(a)(2)(iv)(A), for an event or condition that resulted in the manual actuation of the RPS and RCIC system.</p> <p>Root cause of the event: The overall process for implementation of ICS logic block code changes lacked the required level of process rigor and formality for maintaining digital control systems with the potential to affect reactivity and reactor water level. This challenged the operator's ability to maintain precise control of the plant.</p> <p>Key planned corrective actions: 1) Develop procedural guidance to implement the HURST software configuration management tool for post-maintenance testing of ICS software changes, and 2) Develop procedural guidance for installing/verifying code changes to the ICS software.</p> <p>There were no actual consequences to the health and safety of the public as a result of this event.</p>							

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Susquehanna Steam Electric Station Unit 2	05000388	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 3
		2013	--003--	00	

NARRATIVE**CONDITIONS PRIOR TO THE EVENT**

Unit 1 - Mode 1, 100 percent Rated Thermal Power

Unit 2 - Mode 1, 14 percent Rated Thermal Power

EVENT DESCRIPTION

On September 14, 2013, at approximately 0330 hours, Operations was performing a shutdown of Susquehanna Steam Electric Station (SSES) Unit 2 reactor. With the reactor at 14 percent power, the Feedwater Integrated Control System (ICS) in automatic, and the 'B' Reactor Feedwater Pump (RFP) [EIS Code: SJ] running in standby, the control room operators initiated a transfer of the 'A' RFP from flow control mode (FCM) to discharge pressure mode (DPM). During the transition, the 'A' RFP prematurely entered DPM while the normal discharge valve (HV-20603A) was still open, causing a rapid rise in the reactor pressure vessel (RPV) water level. The operators were unsuccessful in reducing the feedwater flow to the reactor before the water level reached the Level 8 trip setpoint (+54 inches). This resulted in all RFP turbines tripping. The operators subsequently took the mode switch to shutdown to manually scram the reactor.

All control rods inserted. Reactor water level lowered to approximately +18 inches. There were no automatic Emergency Core Cooling System (ECCS) initiations. The Reactor Core Isolation Cooling (RCIC) [EIS Code: BN] system was manually initiated for reactor water level control until a RFP was recovered. No steam relief valve opened during the event. No containment isolations occurred. All safety systems operated as expected. RCIC was manually shut down once a RFP was restored.

In accordance with 10 CFR 50.72(b)(2)(iv)(B), on September 14, 2013, a 4-hour ENS notification (# 49342) was made to the NRC for an event or condition that results in the actuation of the Reactor Protection System (RPS) when the reactor is critical. This event was also reportable as an 8-hour notification in accordance with 10 CFR 50.72(b)(3)(iv)(A) for any event or condition that resulted in a valid actuation of the RPS and the RCIC system. This LER is being submitted in accordance with 10 CFR 50.73(a)(2)(iv)(A) for an event or condition that resulted in the manual actuation of the RPS and RCIC system.

CAUSE OF THE EVENT

Direct Cause – A critical function block in the ICS software was configured incorrectly (i.e., data input error) during software modifications to the Unit 2 Integrated Control System.

Root cause of the event: The overall process for implementation of ICS logic block code changes lacked the required level of process rigor and formality for maintaining digital control systems with the potential to affect reactivity and reactor water level. This challenged the operator's ability to maintain precise control of the plant.

ANALYSIS / SAFETY SIGNIFICANCE**Actual Consequences**

The actual consequence of this event was a reactor scram from 14 percent reactor power during a planned shutdown. There was no nuclear safety, radiological safety, environmental safety, or industrial safety consequences.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Susquehanna Steam Electric Station Unit 2	05000388	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	3 OF 3
		2013	--003--	00	

Potential Consequences

The Unit 2 risk significance and potential consequences for the initiating event experienced on September 14, 2013 due to a loss of feedwater was less than 1E-06 for Core Damage Probability (CDP) and 1E-07 for Large Early Release Probability (LERP) significance thresholds as outlined in NRC Inspection Manual Chapter 609. These thresholds represent a Green significance level and are of "Very Low Safety Significance."

In summary, there were no actual consequences to the health and safety of the public as a result of the event.

CORRECTIVE ACTIONS**Key Completed Corrective Actions:**

- Reviewed software changes made from August 2011 thru September 17, 2013 to the Unit 1 and Unit 2 12 ICS field processors. No coding errors were identified.

Key Planned Corrective Actions:

- Review software changes made to the 12 ICS field control processors prior to August 2011 to verify there are no coding errors.
- Review software modifications made to all other plant systems with digital controls. Ensure proper installation of software via system testing, system operation, line-by-line comparisons, or other methods approved by system engineering management.
- Develop procedural guidance to implement the HURST software configuration management tool for post-maintenance testing of ICS software changes.
- Develop procedural guidance for installing/verifying code changes to the ICS software.
- Review existing task qualifications for the Station Engineering – Computer group and identify any necessary changes based on the current work activities performed by the group.

PREVIOUS SIMILAR EVENTS

LER 388/2012-004-00: Unit 2 Auto Scram on Low RPV Level

LER 388/2012-002-00: Unit 2 Manual Scram Due to Loss of the Integrated Control System

LER 388/2011-003-00: Unit 2 Scram during Performance of ICS Testing

LER 388/2010-002-00: Automatic Reactor Scrams Occur during Post-Modification Testing of the Digital Feedwater Integrated Control System